WEILAND
INDUSTRIAL DOORS & WINDOWS

HEATED WINDOW GUIDE

SCENARIOS 1 & 2





IMPORTANT NOTES FOR HEATED WINDOWS

1. The greatest factor affecting condensation is humidity on the warm side.
2. If the window opening is a similar temperature on each side (cold/cold or warm/warm) a heated window is not necessary.
3. Heated windows are only available for temperatures down to -20˚ F on the cold side.
4. Face-mounted cable connection only available on Glazed/Front-Trim Side.

WEILAND
INDUSTRIAL DOORS & WINDOWS

HEATED WINDOW GUIDE

SCENARIOS 3 & 4





IMPORTANT NOTES FOR HEATED WINDOWS

1. The greatest factor affecting condensation is humidity on the warm side.
2. If the window opening is a similar temperature on each side (cold/cold or warm/warm) a heated window is not necessary.
3. Heated windows are only available for temperatures down to -20˚ F on the cold side.
4. Face-mounted cable connection only available on Glazed/Front-Trim Side.